

Download Electronics Circuit Analysis And Troubleshooting Guide

Alarm 9100 NON RESETTABLE SOFTWARE ERROR at Power On, or Alarm 9915 IO BOARD CONFIGURATION MISMATCH. Alarm 9933 SOFTWARE VERSION MISMATCH and 9100 NON RESETTABLE SOFTWARE ERROR Multiple Alarms or 9924 CONTROL AND IO BOARD COMMUNICATION LOST 9925 CONTROL AND IO BOARD COMMUNICATION DID NOT INITIALIZE and all the input values on the diagnostic page show XX. There are four versions of Haas amplifiers. 30A [1], 45A [2], 60A [3], and 90A [4]. All four operate the same way. Smart Amplifier assemblies are powered from the 320 VDC Bus from the Vector Drive assembly or Minimill Power Supply. There are thirty-three basic fundamental Subject Knowledge, Task Performance and Task Knowledge activities and functions within the NCATT Standards for an Aircraft Electronics Technician (AET). The AET Standards were identified and defined by aerospace industry Subject-Matter-Experts (SMEs) through an NCATT facilitated, industry recognized, occupational SHOP PRACTICES. Knowing about good electronic shop practices begins with introduction to the basic tools and test instruments used in electronic repair, production and troubleshooting. It continues with "hands-on" activity directed towards learning practical skills such as soldering and de-soldering and making connecting leads and cables.