

# Download Allison Troubleshooting Guide

Pushbutton and lever shift selectors for the Allison 4th Generation Series are remote mounted from the TCM and communicate to the TCM via the J1939 communications data link. All shift selectors except the strip-type pushbutton have a dual digit vacuum fluorescent (VF) display and a mode indicator (LED). vehicle manufacturer and/or body builder before servicing the Allison transmission in that vehicle. Proper service and repair is important to the safe and reliable operation of the equipment. The service procedures recommended by Allison Transmission and described in this manual are effective methods for performing troubleshooting operations. OEM TROUBLESHOOTING GUIDE FOR ALLISON WT TROUBLE CODES.

TROUBLESHOOTING WITH DIAGNOSTIC CODES (Additional troubleshooting information can be found in the appropriate Troubleshooting Charts For Allison Transmissions AT / MT (B) / HT / V. The troubleshooting information contained in the following charts outlines the possible causes of transmission conditions and their remedies. Several possible causes are indicated; numbered items indicate suggested remedies for the causes.